FIELD INSPECTION REPORT

Date of Inspection: 3/2 2520 District: Katihar.			
Division: Katihar Length (KM): 4.018 KM			
Name of Road:		Byda Pisa (coeps to to bon and to	
Scheme/ Programme:		MAINTENANCE	
Packa	ge No. MA-N/19	120 KATIAAR ROAD ID No. 21105602012	
Status of the Project:		Onging/Completed/Under Maintenance	
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance	
SLNo		Parameters to be Checked	Remarks
1	Pavement		
a)	Road Junction Condition S/		
b)	Condition of Surfacing		S/U /
c)	Riding Quality		S/U N·
d)	Road Camber		S/U No
e)	Whether free from o	Yes/No N	
f)	Contraction Joints p	Yes/No N	
g)	Compaction of flank/slpoe & raincuts if any		Yes/No N'
2	Cross Drainage		
a)	Condition of headwalls inn Humepipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/U N
c)	Condition of railings/slabs//approach for Bridges S/SRI		S/SRI/U \\^
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained. Yes/No		L_Yes/No
4	Compliance History		
a)			No
Overall	Grading:	Satisfactory (S)	3
		Satisfactory but requires Improvement(SRI)	
		Unsatisfactory (U)	

Name: Mritungo 7 Aumor Degisnation-

R.W.D. Works Div. Katihar