

FIELD INSPECTION REPORT

Date of Inspection: 3/2/2020		District: Katihar.
Division : Katihar		Length (KM) : 10.49 KM
Name of Road:	Nigunda to Sorsil Kurgela Phd road at Nigunda	
Scheme/ Programme:	MAINTENANCE	
Package No. M&N/19-20/KATIHAR/08	Road ID No. 21105602060	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/ Up Gradation/ Maintenance	
SLNo	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S/U N.A
b)	Condition of Surfacing	S/U N.A
c)	Riding Quality	S/U N.A
d)	Road Camber	S/U N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of headwalls in Humepipe culverts including its painting	S/SRI/UN.A
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slabs/approach for Bridges	S/SRI/UN.A
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.	Yes/No
4	Compliance History	
a)	Status of ATR & any others	No
Overall Grading:		S
Satisfactory (S)		
Satisfactory but requires Improvement(SRI)		
Unsatisfactory (U)		

Name: Vijay Kumar
Designation: A.E. Katihar

R.W.D. Works Div., Katihar

(Signature)
03.02.2020