

FIELD INSPECTION REPORT

Date of Inspection: 4.12.2020		District: Kachhar
Name of Road: Pipra to Gaidandga		
Scheme/ Programme: MAINTENANCE		
Package No. MR-N/19-20 Kachhar/2	Road ID No. 211056020 SQ	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/ Up Gradation/ Maintenance		
SLNo	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S/U N.A
b)	Condition of Surfacing	S/U N.A
c)	Riding Quality	S/U N.A
d)	Road Camber	S/U N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of headwalls in Hume pipe culverts including its painting	S/SRI/U N.A
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slabs/approach for Bridges	S/SRI/U N.A
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.	Yes/No
4	Compliance History	
a)	Status of ATR & any others	No

Overall Grading:

Satisfactory (S)	S
Satisfactory but requires Improvement(SRI)	
Unsatisfactory (U)	

Name:
Designation

Minjonyy Kumar
Junior Engineer

(Signature)

4/12/2020