

FIELD INSPECTION REPORT

Date of Inspection: 3/12/2020		District: Katihar.	
Division : Katihar		Length (KM) : 3.060 KM	
Name of Road:		Sorgi Kusele road to Simen's	
Scheme/ Programme:		MAINTENANCE	
Package No. MA-N/17-20 KATIHAR/08		Road ID No. 21105602062	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance	
SLNo	Parameters to be Checked		Remarks
1	Pavement		
a)	Road Junction Condition		S/U N/A
b)	Condition of Surfacing		S/U N/A
c)	Riding Quality		S/U N/A
d)	Road Camber		S/U N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)		Yes/No N/A
g)	Compaction of flank/slope & raincuts if any		Yes/No N/A
2	Cross Drainage		
a)	Condition of headwalls in Humepipe culverts including its painting		S/SRI/U N/A
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/U N/A
c)	Condition of railings/slabs/approach for Bridges		S/SRI/U N/A
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		Yes/No
4	Compliance History		
a)	Status of ATR & any others		11
Overall Grading:		Satisfactory (S)	S
		Satisfactory but requires Improvement(SRI)	
		Unsatisfactory (U)	

Name: Mritunjay Kumar
 Designation: Junior Engineer
 R.W.D. Works Div., Katihar

(Signature) [Signature]
 3/12/2020