

FIELD INSPECTION REPORT

Date of Inspection: 3/12/2020		District: Kishangang	
Division: Kishangang-1		Length(km): 1.820 km	
Name of the Road: 13th km of T03 to Jhangidighi			
Scheme/Programme: MAINTENANCE			
Package No.: RM/KI/KIS/19/0006		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance (In Agreement process)	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	
S1. No	<u>Parameters to be checked</u>		Remarks
1.	Pavement		S/U
a)	Road Junction Condition	Work not started yet. (In Agreement process)	S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		NA Yes/No
f)	Contraction Joints Provided or not (CC Pavement)		NA Yes/No
g)	Compaction of fland / shop & raincuts if any		not started Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting		S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		Not started S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		NA Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		-

Overall Rating :

Satisfactory(S)	NA
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-


 3/12/20
 (Signature)

NAME: Ranjeet Kumar
 AE, RWD, (W) (Sub-Div)
 Kochadhaman