## FIELD INSPECTION REPORT

| Date of                | Inspection: 👓 -  | 12.020   | District: Kishansans           |           |  |
|------------------------|--|--|--------------------------------|-----------|--|
| Division: KishanganT-1 |  |  | Length(km): 2-850 Km.          |           |  |
| Name o                 | of the Road: ೪ಟ  | to Road the  | edeal Andhasur.                |           |  |
|                        | e/Programme:   | MAINTENANCE  | New MX                         |           |  |
| Package                | e No.: RM/KI/  | KIS/19/0007  | Road Id No.:                   |           |  |
| Status o               | of the Project:  | The second secon | eted /Under Maintenance        |           |  |
| Work is                | a case of:   | The state of the s | ty/ Up gradation / Maintenance |           |  |
| \$1. No                |  |  | to be checked                  | Remarks   |  |
| 1.                     | Pavement   |  |                                | N S/U     |  |
| a)                     | Road Junction Condition  |  |                                | VS/U      |  |
| b)                     | Condition of Surfacing   |  |                                | VS/U      |  |
| c)                     | Riding Quality   |  |                                | VS/U      |  |
| d)                     | Road Camber  |  |                                | LS/U      |  |
| e)                     | 140 11 6 6 16  |  |                                | Yes/No    |  |
| f)                     | Contraction Joints Provided or not ( CC Pavement)  |  |                                | NA Yes/No |  |
| g)                     | Compaction of fland / shop & raincuts if any   |  |                                | 1 Yes/No  |  |
| 2.                     | Cross Drainage   |  |                                |           |  |
| a)                     | Condition of head walls in Hume pipe culverts including its Painting   |  |                                | √ S/SRI/U |  |
| b)                     | Condition of Abutment & Wing walls, slab in RCC culverts   |  |                                | S/SRI/U   |  |
| c)                     | Condition of railings/Slab/approach for Bridges  |  |                                | S/SRI/U   |  |
| 3.                     | Road Furniture   |  |                                |           |  |
| a)                     | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained |  |                                | Yes/No    |  |
| 4.                     | Compliance History   |  |                                |           |  |
| a)                     | Status of ATR's & any others   |  |                                | NO ATR    |  |

## Overall Rating:

| Satisfactory(S)                             | <u>'S'</u> |
|---|------------|
| Satisfactory but requires Improvement (SRI) | •          |
| Unsatisfactory(U)                           | -          |

IE

(Signature)

NAME: