

FIELD INSPECTION REPORT


Date of Inspection: 02.12.2020.		District: Kishanganj.	
Division: Kishanganj-1		Length(km): 5.94 km.	
Name of the Road: To S-Handi bhaga - Handi bari.			
Scheme/Programme:		MAINTENANCE New MR	
Package No.: RM/KI/KIS/19/0007.		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	

Sl. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	NA Yes/No
g)	Compaction of fland / shop & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory(S)	(S)
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-


 02.12.2020
 IE


 2/12/20
 (Signature)
 AE

NAME: