FIELD INSPECTION REPORT

	Inspection: 03.		District: Kighansans	
Division	n: kishansant-1		Length(km): 2.96 km	
			Shahamsaon	
Scheme	/Programme:	MAINTENANCE		
Package	No .: RM/KE/	KIS/19/0007	Road Id No.:	
Status o	f the Project:		leted /Under Maintenance	
	a case of:		ty/ Up gradation / Maintenance	
51. No			s to be checked	Remarks
1.	Pavement			V5/U
a)	Road Junction Condition			VS/U
b)	Condition of Surfacing			1/5/U
c)	Riding Quality			1/S/U
d)	Road Camber			1/5/U
e)	1.00			
	in case of CC Pa	evement.	os visible crucks, exposed aggregates	N/A Tes/Ito
f)	Contraction Joints Provided or not (CC Pavement)			NA Yes/No
g)	Compaction of fland / shop & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its Painting S/SR			S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts			✓S/SRI/U
c)	Condition of railings/Slab/approach for Bridges			S/SRI/U
3.	Road Furniture			7
a)	Whether sign boards/informatory/cautionary Board/km & 200m			Yes/No
	stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's	& any others		NO ATR
	Rating :			Pen

Overall Rating:

Satisfactory(S)	'C'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	_

NAME: