

FIELD INSPECTION REPORT

Date of Inspection: 3/12/2020		District: Kishanganj	
Division: Kishanganj-1		Length(km): 1.00 km	
Name of the Road: Sontha D.B. 50 to Sontha P.W. D. Road			
Scheme/Programme: MAINTENANCE			
Package No.: RM/KI/KIS/19/0006		Road Id No.: -	
Status of the Project:		Ongoing/Completed /Under Maintenance (In Agreement Process)	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	

Sl. No	Parameters to be checked	Remarks
1.	Pavement	S/U
a)	Road Junction Condition	S/U
b)	Condition of Surfacing	NA S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	Yes/No
g)	Compaction of fland / shop & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory(S)	NA
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-


 (Signature)

NAME: Ranjeet Kumar
 AE