

FIELD INSPECTION REPORT

Date of Inspection :- 2.12.2020 District :- Nalanda
 Division :- Rajgir Length (km): - 5.700 k.M
 Name of the Road:- Veraitth to Koyanibighe via Govardhan Bigho.
 Scheme/Programme: MAINTENANCE (3054 MR) New Maintenance Policy - 2018.
 Package No.: - RA/NA/Raj/2019/601. Road Id No.: - 10200601013.
 Status of the Project: Ongoing Completed Under Maintenance Ongoing.
 Work is a case of: New Connectivity Up gradation Maintenance Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U (Work in progress)
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (✓) (NA)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (✓) (NA)
g)	Compaction of flank slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (Work in progress)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No (Work in progress)
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)

S

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)


 2.12.20
 (Signature)

NAME :- Kishor Kumar
 Assistant Engineer
 Kabinisara.