

FIELD INSPECTION REPORT

Date of Inspection : 31/12/20 District: Nalanda.
 Division : Patna Length (km): 1.80 km
 Name of the Road: Tol - Bazithen to Bhagwanpur road
 Scheme/Programme: MAINTENANCE Sanctioned in PMBSY-II
 Package No.: Road Id No.:
 Status of the Project: Ongoing Completed/Under Maintenance
 Work is a case of: New Connectivity Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/I
b)	Condition of Surfacing	S/I
c)	Riding Quality	S/I
d)	Road Camber	S/I
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings-slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	


Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Sakunt Kumar
 NAME:


 (Signature) 31/12/20
 Jf