


FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District:	Nalanda
Division :	Rajgir	Length (km):	0.9 km
Name of the Road:	Rajgir giriyak road to thakurstan road		
Scheme/Programme:	MAINTENANCE	(3054 MR)	
Package No.:	Batch RM/NA/RAJ/19/0005	Road Id No.:	1020060/022
Status of the Project:	Ongoing/Completed/Under Maintenance	Ongoing. (Gr-II) in progress	
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (NA) ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (NA) ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (NA) ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (NA) ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U (NA) ✓
3.	Road Furniture	
a)	Whether sign ✓ boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained ✓	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


3.12.20
(Signature)

NAME: - Kishor Kumar
Assistant Engineer
Rajgir.