FIELD INSPECTION REPORT

Date of Inspection: 03.12.2020 Distrcit: SARAN

Division: SONPUR Length (km): 4.580

Name of the Road: Parsa Bankerwa R.E.O. road to babhan gama via marar bazar

Scheme/Programme: MAINTENANCE

Package No: Road ID No:

Status of The Project: Completed

Work is a case of: Maintenance

SI.No	Parameters to be checked	Remarks
	Pavement	
1		S
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed	YES
	aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	YES
g)	Compaction of Flank/slope & raincuts if any	YES
2	Cross Drainage	
a)	Condition of head walls in Hume pipe Culverts including its painting	S
b)	Condition of Abutment & Wing Walls, Slab in RCC Culverts	S
C)	Condition of railings/slab/approach for Bridges	S
3	Raod Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	YES
4	Compliance History	
a)	Status of ATR's any others	NO

Overall Rating:

Satisfactory (S) Satisfac	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

8ignature

NAME:- RAJEEV RANJAN KUMAR
DESIGNATION: JUNIOUR ENGINEER