

FIELD INSPECTION REPORT


Date of Inspection : 04.12.2020		District: Chapra (Gharan)
Division : Maechuan		Length (km): 3.731
Name of the Road: Katska School to Raspara.		
Scheme/Programme: MAINTENANCE		
Package No.: AM/SA/MAA/10/600/		Road Id No.: 31306202051
Status of the Project: Ongoing/Completed/Under Maintenance - Completed.		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/UXS
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	Yes
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	ND.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

At some places surface damage due to rain & food.
 Now road is motable at damage points. Rest is ok.

Abdul Manan Khan
 NAME:
 DESIGNATION: J.E

(Signature) 
 04/12/2020
 J.E. Armon