

FIELD INSPECTION REPORT

Date of Inspection :	03.10.2020	District:	SARAY
Division :	MARHAURA	Length (km):	6.40
Name of the Road:	Jagajyoti to Hahan An Bagan Road under (3054) M/R		
Scheme/Programme:	MAINTENANCE		
Package No.:	RA/SA/MAR/17/0010	Road Id No.:	31306202109
Status of the Project:	Ongoing/Completed/Under Maintenance ongoing		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ongoing
2.	Gross Draining	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U RA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ongoing
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Shree Ram Das

DESIGNATION:

Assistant Engineer

(Signature)

03.12.2020