## FIELD INSPECTION REPORT

		FIELD INSPEC	HOWKEN		
ate of In	spection: o	4/12/2020	Murici: Nalanda		
Division: Bolhan Charle			Length (km): 2,40		
ame of t	he Road: Mi	+31 TO Rahm &	Tanewal Sadak se sal How maintenance police	ampur	
cheme/l'	rogramme:	MAINTENANCE	How maintenance part	7-1018	
ackage l			Road Id No.:		
	the Project:	Ongoing/Completed	l/Under Maintenance Op gradation/ Maintenance		
	e case of:	Parameters to		Remarks	
SI. No.		Parameters to	DE CHECKER		
1.	Pavement				
a)	Road Junction condition				
b)	Condition of Surfacing			S/U	
<u> </u>	Riding Quality			S/U	
<u> </u>	Paril Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
	Contraction Joints provided or not (CC Pavement)			Yes/No	
(g	Compaction of flank/slope & raincuts if any			Yes/No	
2.5	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
<u>a)</u>	Condition of Abutment & Wing walls, Slab in RCC culverts  S/SRI/U				
ь)	Condition of railings/slah/approach for Bridges			S/SRI/U	
c)					
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
2715	Compliance	History		1 11	
a)		R's & any others		Hil	
-,					

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Bired Kumer Work

DESIGNATION: J. 尼

Scanned with CamScanner

Scanned with CamScanner