

FIELD INSPECTION REPORT

Date of Inspection : 04-12-20	District: Sado
Division : R.H.D. CHAPER-2	Length (km): 3.970 Km
Name of the Road: Houshejpur Khurd to Houshejpur	
Scheme/Programme:	MAINTENANCE
Package No.: M/R-N 9-20-CHAP-2/01	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1. Road Surface		
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2. Culverts & Bridges		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4. Compliance with ATR		
a)	Status of ATR's & any others	N.D.

Overall Rating :

Satisfactory (S)	Yes
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: .

DESIGNATION:

04/12/20
AE
Banyalpur

(Signature)
12/20
Banyalpur