

FIELD INSPECTION REPORT

Date of Inspection :	4.12.20	District:	SARAN
Division :	MARHORA	Length (km):	5.894 K.M
Name of the Road:	GOPALPDR TO DEBBANVARA		
Scheme/Programme:	MAINTENANCE		
Package No.:	AM/SA/MAR/19/0003	Road Id No.:	31306402030
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	-S/U
b)	Condition of Surfacing	-S/U
c)	Riding Quality	-S/U
d)	Road Camber	-S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <u>HA</u>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <u>HA</u>
g)	Compaction of flank/slope & raincuts if any	<u>Yes</u> /No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <u>N.A</u>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<u>Yes</u> /No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


NAME: 4.12.20
DESIGNATION:
JE


(Signature)