

FIELD INSPECTION REPORT

Date of Inspection : 4/12/20	District: SARAN
Division : MARIHORA	Length (km): 2.762 K.M
Name of the Road: KARAMPURA SE BIKRAMPUR	
Scheme/Programme: MAINTENANCE	
Package No.: RM/SA/MAR/19/0004	Road Id No.: 31306402033
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No H.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No H.A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :


Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Amit K Chaudhary

NAME: 4.12.20

DESIGNATION:

PC


(Signature)