

FIELD INSPECTION REPORT

Date of Inspection : 3.12.2020	District: SARAN
Division : MARHAURA	Length (km): 10.52 km
Name of the Road: Pirari to Damodarapur Road under 3054 (MR)	
Scheme/Programme: MAINTENANCE	
Package No.: AM/SA/MAR/10/0016	Road Id No.: 31306402065
Status of the Project: Ongoing/Completed/Under Maintenance	Ongoing
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl.No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No Ongoing
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No Ongoing
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Devendran Kumar
NAME: Assistant Engineer
DESIGNATION:

De
3.12.2020
(Signature)