FIELD INSPECTION REPORT

FIELD INSPECTION AS	
w A 10 Och I Trintmoti	
1CV	
f the Project: Ongoing/Completed/Under Maintenance	
a case of: New Connectivity/Up gradation/ Maintenance	
Parameters to be dheeked	Romines
Pavement	A STATE OF THE STA
Road Junction condition	✓S/U
	√S/U
	√\$/U
	√S/U
	Yes/No
aggregates in case of CC Pavement.	
Contraction Joints provided or not (CC Pavement)	Yes/No
Compaction of flank/slope & raincuts if any	✓Yes/No
Cross Drainage	
Condition of head walls in Hume pipe culverts including its painting	g /S/SRI/U
Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
Condition of railings/slab/approach for Bridges	✓S/SRI/U
Road Furniture	
Whether sign boards/informatory/cautionary Board/km & 200 stones/Pavement road markings are provided and maintained	m Yes/No
Compliance History	
Status of ATR's & any others	NO ATR
	Inspection: 9-12-2020 District: 99790 Fithe Road: To 5 to Pary O Programme: MAINTENANCE Road Id No.: f the Project: Ongoing/Completed/Under Maintenance a case of: New Connectivity/Up gradation/ Maintenance Programme: Waintenance Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any Gross Dininge Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Road Firmiture Whether sign boards/informatory/cautionary Board/km & 200 stones/Pavement road markings are provided and maintained Gompliance History

Overall Rating

Satisfactory (S)	13/
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Priore

(Signature)

NAME: Yogesh Chandra mishor DESIGNATION: Assistant Egineer