

**FIELD INSPECTION REPORT**

BLOCK- Jalalpur

|                        |                                            |              |                |
|------------------------|--------------------------------------------|--------------|----------------|
| Date of Inspection :   | 03.12.2020                                 | District:    | Saran (chapra) |
| Division :             | chapra-2                                   | Length (km): | 6.10 km        |
| Name of the Road:      | Tarwa to Patila                            |              |                |
| Scheme/Programme:      | MAINTENANCE                                |              |                |
| Package No.:           |                                            | Road Id No.: |                |
| Status of the Project: | Ongoing/Completed/Under Maintenance        |              |                |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |                |

| Sl. No. | Parameters to be checked                                                                                             | Remarks   |
|---------|----------------------------------------------------------------------------------------------------------------------|-----------|
| 1.      | <b>Pavement</b>                                                                                                      |           |
| a)      | Road Junction condition                                                                                              | ✓ S/U     |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U     |
| c)      | Riding Quality                                                                                                       | ✓ S/U     |
| d)      | Road Camber                                                                                                          | ✓ S/U     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓ Yes/No  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No    |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No  |
| 2.      | <b>Cross Drainage</b>                                                                                                |           |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ S/SRI/U |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U   |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U   |
| 3.      | <b>Road Furniture</b>                                                                                                |           |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No  |
| 4.      | <b>Compliance History</b>                                                                                            |           |
| a)      | Status of ATR's & any others                                                                                         | NO ATR    |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) | — |
| Unsatisfactory (U)                          | — |

Mritunjay Kumar

Mritunjay Kumar  
03/12/20  
(Signature)

NAME:

DESIGNATION:

(J.E)