

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District:	Siwan
Division :	Siwan-01	Length (km):	
Name of the Road:	Siwan-Hasua path se Mura Tak		
Scheme/Programme:	MAINTENANCE	MR 3054	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Not Provided
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	yes Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	Not provided S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m yes Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Shambhu
04.12.2020
(Signature) JE/Siwan-01

NAME: SHAMBU KUMAR THAKUR
Junior Engineer