

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District:	Siwan
Division :	Siwan-01	Length (km):	
Name of the Road:	Siwan-mainwa BT path se Naurapali		
Scheme/Programme:	MAINTENANCE MR 3054		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U S
b)	Condition of Surfacing	✓S/U S
c)	Riding Quality	✓S/U S
d)	Road Camber	✓S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Not provided
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U Net provided
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓Yes/No yes
4.	Compliance History	
a)	Status of ATR's & any others	ND ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Shambhu
04.12.2020
JE/Siwan-01
(Signature)

NAME: SHAMBHU KUMAR THAKUR
Junior Engineer