


FIELD INSPECTION REPORT

Date of Inspection :		District: Siwan
Division :		Length (km): at 1/50KM
Name of the Road: Mahadeva Ghurdan Road & Siwan-Lateri-Dargah Road Mahadeva Ghurdan Road		
Scheme/Programme: MAINTENANCE		OP to Bazaria Road
Package No.:		Road Id No.:
Status of the Project: ☒ Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U S
b)	Condition of Surfacing	✓ S/U S
c)	Riding Quality	✓ S/U S
d)	Road Camber	✓ S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No Provisions
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No Yet To be done
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U Yet To be done
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U Yet To be done
c)	Condition of railings/slab/approach for Bridges	S/SRI/U No Provisions
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)	✓ S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

For 
(Signature)

NAME: Manoj Kumar

DESIGNATION: E E RUPDSwami