

FIELD INSPECTION REPORT

Date of Inspection :	4/12/2020	District:	SIWAN
Division :	RKD SIWAN-01	Length (km):	12.800 km
Name of the Road:	SH-47 Bazarahia Sarafa Balkishun Sybil's House To Pehra Kalvia Hanumantpura (MIR)		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	S
b)	Condition of Surfacing	✓ S/U	S
c)	Riding Quality	✓ S/U	S
d)	Road Camber	✓ S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	No provision
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No	work is being done
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	work is being done
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U	S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	S
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	✓ S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

For Gup
(Signature) 4/12/2020

NAME: Manoj Kumar
DESIGNATION: EERKD. Siwan 01