

FIELD INSPECTION REPORT

Date of Inspection :		District: <u>Gopalgarh</u>
Division : <u>W.D. Gopalgarh-02</u>		Length (km): <u>3.50 KM</u>
Name of the Road: <u>Danapur to Manjha Bazar</u>		
Scheme/Programme: <u>MAINTENANCE</u>		
Package No.:		Road Id No.:
Status of the Project: <u>Ongoing/Completed/Under Maintenance</u>		
Work is a case of: <u>New Connectivity/Up gradation/ Maintenance</u>		
Sl. No.	Particulars	Remarks
1. Pavement		
a)	Road Junction condition	<u>S/U</u>
b)	Condition of Surfacing	<u>S/U</u>
c)	Riding Quality	<u>S/U</u>
d)	Road Camber	<u>S/U</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<u>Yes/No</u>
f)	Contraction Joints provided or not (CC Pavement)	<u>Yes/No</u>
g)	Compaction of flank/slope & raincuts if any	<u>Yes/No</u>
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	<u>S/SRI/U</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<u>S/SRI/U</u>
c)	Condition of railings/slab/approach for Bridges	<u>S/SRI/U</u>
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<u>Yes/No</u>
4. Compliance History		
a)	Status of ATR's & any others	<u>N.A.</u>

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	<u>✓</u>
Unsatisfactory (U)	

Note:- The Some part of Road from CH-2000m to CH-2500m affected from water logging

Rajesh Kumar
(Signature)

NAME:

Rajesh Kumar
- J.E.