SA

FIELD INSPECTION REPORT

	Inspection : 5	3/14 rovo	District: MusaMerrous	-	
Division: RWD Length (km): 3,670			m		
The second second second second	of the Road: C	Liking Gra	my to ladera		
The same of the sa	/Programme:	MAINTENANC	and the same of th		
			Road Id No.:	and the second s	
Status of the Project: Queening/Completed/Under Mainten Work is a case of: New Connectivity/Un gradation/ Ma					
	a case or;	-	y/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks		
1.	Pavement				
a)	Road Junction condition			S/U AA	
b)	Condition of Surfacing			S/U NA	
c)	Riding Quality			S/U HA	
d)	Road Camber			S/U AA	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No MA	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No HA	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/LI	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
9.1	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No HA	
4.	Compliance History			463	
a) !	Status of ATR's & any others				
overall R	ating :	Satisfactory (S)		Hew Mai tens	
		Satisfactory but Unsatisfactory (I	requires Improvement (SRI)		

NAME: Md Nayor Alac

DESIGNATION: J.E.

K autoh
03/12/2020

(Signature)

A.E., R.W.