

FIELD INSPECTION REPORT

FIELD INSPECTION REPORT

Date of Inspection : 04/12/2020		District: MUZAFFARPUR	
Division : RWD WEST		Length (km): 8.75	
Name of the Road: Narsanda - Manikpur Narottam			
Scheme/Programme:		MAINTENANCE	
Package No.: RM/MU/MUZ/20/0002		Road Id No.: 31507202203	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	


Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition N/A	S/U
b)	Condition of Surfacing N/A	S/U
c)	Riding Quality N/A	S/U
d)	Road Camber N/A	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N/A	Yes/No
f)	Contraction Joints provided or not (CC Pavement) N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any N/A	Yes/No
2.	Cross Drainage N/A	
a)	Condition of head walls in Hume pipe culverts including its painting N/A	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges N/A	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained N/A	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)


 04/12/2020
 (Signature)

NAME: Raman Krishna

DESIGNATION: AE