PIELD INSPECTION REPORT Date of Inspection: 04/12/2020 District: Muzapparpur Division: RWD Length (km): 1.46 WEST Name of the Road: Sahbajpur Pitch Road - Mirjapur Scheme/Programme: MAINTENANCE Road Id No.: 3150720 2256 Package No.: RM/MU/MUZ/19/0023 Ongoing/Completed/Under Maintenance Status of the Project: New Connectivity/Up gradation/ Maintenance Work is a case of: Remarks Parameters to be checked SI. No. Pavement 1. SIU NIA Road Junction condition a) SIU H/A Condition of Surfacing b) SIU H/A Riding Quality c) SIU MA Road Camber d) exposed Whether free from defects such as visible cracks, Yes/No H/A aggregates in case of CC Pavement. e) Yes/No Contraction Joints provided or not (CC Pavement) N/A. f) Yes/No NIA Compaction of flank/slope & raincuts if any g) Cross Drainage 2. Condition of head walls in Hume pipe culverts including its painting MAS/SRI/U a) S/SRI/U Condition of Abutment & Wing walls, Slab in RCC culverts HIA b) S/SRI/U Condition of railings/slab/approach for Bridges H/A

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

Overall Rating

c)

3.

a)

4.

a)

| Satisfactory (S) | |
|---|--|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

(Signature)

Yes/No

MOATR

NAME: Raman Krishang

Road Furniture

Compliance History

Status of ATR's & any others

DESIGNATION: AL