## FIELD INSPECTION REPORT

		District: Varaboli
Division: Ida Aus		Length (km): 2.75 k. 1
		Exercise
Name of the Road:	halomansor	to Hussainpur
Scheme/Programme:	MAINTENANCE	
Package No :		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/	Up gradation/ Maintenance

Work is a case of:		New Connectivity/Op gradations in attriction	
SI. No.	140 (800)	Parameters to be checked	Remarks
1.	Pavement		A
a)	The state of the s		√S/U
b)	Condition of Surfacing		VS/U
c)	Riding Quality		V8/U
d)	Road Camber		V8/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No 7
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2	Cross Drai	nuge	erton de
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)		of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)		of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furn	liture	
a)	Whether si	ether sign boards/informatory/cautionary Board/km & 200m  Yes/No	
4	Comptinue	a History	A.S.
a)	Status of A	TR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME:

DESIGNATION: