

FIELD INSPECTION REPORT

Date of Inspection :	5/12/20	District:	Vishakhapatnam
Division :	HSTP	Length (km):	3.510 km
Name of the Road:	Kutubla to Simra dhal		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing Completed Under Maintenance		
Work is a case of:	New Connectivity Up gradation Maintenance		

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	NA
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible crack exposed aggregates in case of CC Pavement.	Yes No } NA
f)	Contraction Joints provided or not (CC Pavement)	Yes No }
g)	Compaction of flank/slope & raincuts if any	Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SSRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SSRI
c)	Condition of railings/slab approach for Bridges	SSRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200 m stones Pavement road markings are provided and maintained	Yes No
4.	Compliance History	
a)	Status of ATR's & any others	200 mtr damage in flood.

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

(Signature)

NAME:

DESIGNATION:

[Handwritten Signature]
HSTP
JOC