

FIELD INSPECTION REPORT

Date of Inspection :	4/12/20	District:	Vijaynagar
Division :	Hajliha	Length (km):	0.29
Name of the Road:	Puccikason of road in Shyambur Vill from Phary road to bage river bank via lake near Shyambur village		
Scheme/Programme:	MAINTENANCE (HAB)	Road Id No.:	
Package No.:			
Status of the Project:	Ongoing Completed Under Maintenance		
Work is a case of:	New Connectivity Up gradation/ Maintenance		

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No
f)	Contraction Joints provided or not (CC Pavement)	Yes No
g)	Compaction of flank/slope & raincuts if any	Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its pointing	S SRI I
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI I
c)	Condition of railings slab approach for Bridges	S SRI I
3.	Road Furniture	
a)	Whether sign boards informatory cautionary Board km & 200 stones Pavement road markings are provided and maintained	Yes No (In Progress)
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

(Signature)

NAME:

DESIGNATION:

[Handwritten Signature]