

FIELD INSPECTION REPORT

Date of Inspection :	04/12/20	District:	Vaishali
Division :	Highway	Length (km):	
Name of the Road:	Vaishali Bypass Muttigal to Patanpur		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing Completed Under Maintenance		
Work is a case of:	New Connectivity Up gradation Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S S
b)	Condition of Surfacing	✓ S S
c)	Riding Quality	✓ S S
d)	Road Camber	✓ S S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ S S } NA
f)	Contraction Joints provided or not (CC Pavement)	✓ S S
g)	Compaction of flank slope & raincuts if any	✓ S S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SR11
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SR11
c)	Condition of railings slab approach for Bridges	S SR11
3.	Road Furniture	
a)	Whether sign boards informative cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes No No
4.	Compliance History	
a)	Status of ATR's & any other-	

Overall Rating : SM

Satisfactory (S)	
Satisfactory but requires Improvement (SR1)	<u>SLT</u>
Unsatisfactory (U)	

[Signature]
Signature

NAME:

DESIGNATION: