FIELD INSPECTION REPORT

Date of li	nspection: 02	2/12/20	District: Natanda	
Division: Biharshan			Length (km): 0.740 km	
Name of	the Road: N	H-82 Husaine	a Road to Bari Missian Village	*****
Scheme/	rogramme:	MAINTENAN	CU	
Package	- ' ' ' ' '	N/19-20	Road Id No.:	
Status of the Project: Work is a case of:		Onguing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
	a case of:			No.
Sl. No.		Paramete	ers to be checked	Remarks
1.	Pavement		The second secon	
a)	Road Junction condition			S/U
b)	Condition of Surfacing			3/U
c)	Riding Quality			S/U
d)	Road Camber	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction J	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any			Yes/No-
2.	Cross Drain	age .		
a)	Condition of	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of	Condition of railings/slab/approach for Bridges		
. 3.	Road Furni	ture		
a)	Whether sign stones/Paver	Yes/No		
7				

Overall Rating

Satisfactory (S)	5	
Satisfactory but requires Improvement (SRI)		S
Unsatisfactory (U)		

(Signature)

140

NAME: Mojib Ahmad

Compliance History

Status of ATR's & any others

DESIGNATION: J.E.

Scanned with CamScanner