FIELD INSPECTION REPORT

Date of Inspection: 02 12/20 District: Nalanda			District: Nalanda		
Division: Bilarstant			Length (km): 4.1901cm		
		armera - Pyar	rour your		
	Programme:	MAINTENANCE			
Package No.: MR-N/19-20, By Lass bridge Road Id No.:					
	f the Project:		ed/Under Maintenance		
	n case of:		/Up gradation/ Maintenance		
Sl. No.		Parameters	to be checked	Remarks	
1.	Pavement				
n)	Road Junction condition			S/U	
p)	Condition of Surfacing			\$/U	
c)	Riding Quality			5/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
20	Cross Draina	ge.			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SPIAU	
c)	Condition of railings/slab/approach for Bridges			S/SRIAI	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
N.F.	Compliance History				
a)	Status of ATR's & any others			40	
Carlotten L.					

Overall Rating

Satisfactory (S)	9
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Mojib Ahmad

DESIGNATION: JE