

FIELD INSPECTION REPORT

Date of Inspection: 2-12-2020 District: Nalanda
 Division: Harcourt Length (km): 5.95 Km
 Name of the Road: NH 31 Sec To 4 Narinhor Sarai road Tak via Karmura
 Scheme Programme: T.V. Road Scheme mandalch.
 Package No: Road Id No:
 Status of the Project: Ongoing Completed Under Maintenance ✓
 Work is a case of: New Construction Upgradation Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Condition of Pavement	✓ SRI
b)	Condition of Surfacing	SRI ✓
c)	Rolling Quality	✓ SRI
d)	Roller Camber	✓ SRI
e)	Whether free from defects such as visible cracks exposed aggregates in case of CC Pavement.	✓ Yes No
f)	Contraction Joints provided or not (CC Pavement)	Yes No ✓
g)	Compaction of flank/slope & rancuts if any	Yes No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI ✓
c)	Condition of railings/slab approach for Bridges	S SRI ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 20m stones/Pavement road markings are provided and maintained	Yes No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Ajay Kumar Verma
 02/12/2020
 (Signature)

NAME:

Ajay Kumar Verma

DESIGNATION:

J.E.