

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020		District: Nalanda	
Division : Harnaut		Length (km): 8.4km	
Name of the Road: NH30A to Ramghat-Lohanda via Lakhubigha.			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition S	S/U
b)	Condition of Surfacing SRI	S/U
c)	Riding Quality SRI	S/U
d)	Road Camber S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. NO	Yes/No
f)	Contraction Joints provided or not (CC Pavement) NO	Yes/No
g)	Compaction of flank/slope & raincuts if any NO	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting U	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts SRI	S/SRI/U
c)	Condition of railings/slab/approach for Bridges N/A.	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	X


 (Signature) 02.12.2020

NAME: RAVI KUMAR

DESIGNATION: Sr. Engineer