

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020	District: East Champaran
Division : pakridya	Length (km): 4.20
Name of the Road: Garahiya to mixing Link Road (mathubon - Garahia)	
Scheme/Programme: MAINTENANCE	MR 3054 (New maintenance policy 2018)
Package No.: MR-N/19-20	Road Id No.:
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance	
Work is a case of: ☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	LSAU
b)	Condition of Surfacing	LSAU
c)	Riding Quality	LSAU
d)	Road Camber	LSAU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	LS/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	LS/SRI/U
c)	Condition of railings/slab/approach for Bridges	LS/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

by
03.12.2020
(Signature)

NAME: Dharmendra Kumar
03.12.2020

DESIGNATION: JE