## FIELD INSPECTION REPORT

Date of	Inspection: 03-12-2020 District: Wast champa	Yan
Divisio	I anoth a	cm.
	Tthe Road: Marketing Gran to Mahuaus Porce	
	Frogramme: MAINTENANCE	-
	e No.: RM WB/NAR 0015 Road Id No.: 31868865	2102
	of the Project: Ongoing/Completed/Under Maintenance	
CALL PROPERTY.	s a case of: New Connectivity/Up gradation/ Maintenance	
SI. No.	Parameters to be checked	Remarks
1.	Payement	authorist No.
a)	Road Junction condition	S
b)	Condition of Surfacing	5
c)	Riding Quality	_S .
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	HA
f)	Contraction Joints provided or not (CC Pavement)	MA
g)	Compaction of flank/slope & raincuts if any	Ho
2.	Cross Drainage	15 146
a)	Condition of head walls in Hume pipe culverts including its painting	5
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	٤
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	<u></u>
Unsatisfactory (U)	

(Signature)

NAME: YUAY PRATA PSINGH

DESIGNATION: JE