-	Service Control of the Control of th	AND LECTION RELOAD	The second secon	
Date	of Inspection:	3.12	Land A	
Divis	ion .	1.61	<u>an</u>	
Nam	e of the Road:	tial Length (km):		
C. C.		Bettiah Namajon to Koirgana		
Pack	oge No :	MAINTENANCE		
Package No.: Status of the Project: Ongoing/Compl		Road Id No.:	Road Id No.:	
Work is a case of:		Ongoing/Completed/Under Maintenance		
A 150 10	Company of the second s	New Connectivity/Up gradation/ Maintenance		
SLAN		Baramererato he checked	Remarks	
1	Payement		Nemains	
	THE REPORT OF THE PARTY OF THE		Alternation	
a)	Road Junction condition		S/U	
b)	Condition of Surfacing			
			S/U	
c)	Riding Quality		S/U	
d)	Road Camber			
	Whather for	A 1.C.	S/U	
e)	aggregates in c	from defects such as visible cracks, exposed ase of CC Pavement.	Yes/No	
f)		nts provided or not (CC Pavement)	Yes/No	

Condition of head walls in Hume pipe culverts including its painting

Whether sign boards/informatory/cautionary Board/km & 200m

Condition of Abutment & Wing walls, Slab in RCC culverts

stones/Pavement road markings are provided and maintained

## **Overall Rating**

g)

a)

b)

c)

a)

a)

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Yes/No

S/SRI/U

S/SRI/U

S/SRI/U

Yes/No

NO

(Signature)

Compaction of flank/slope & raincuts if any

Condition of railings/slab/approach for Bridges

Cross Drainage

Road Furniture

Compliance History

Status of ATR's & any others

NAME: Ram Dular Chanhais
DESIGNATION: Juio Engineer