## FIELD INSPECTION REPORT

Date of Inspection: 3.12.2020			District: West Champaran.  Length (km):  Nowallows to Ramparan.	
Division:			Length (km):	
	of the Road:	Bettiah		wa
	e/Programme:	MAINTENANCE	Pood Id No.: 31808902026	
TRANSPORT OF THE PARTY OF		E /BET /19/0013	Mond to	
_	of the Project:	Ongoing/Complet	ed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance		Remarks
SIANO		Patameters	OTBE SHECKED	
	Pavement		The second secon	-
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
<u>d)</u>	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any			
2)	eossidaine			Name of the Party of the Association of the Associa
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
111				TA STATE OF THE ST
a)	Whether sign stones/Pavemen	boards/informatory troad markings ar	//cautionary Board/km & 200m e provided and maintained	Yes/No
	Compliant Calif	ios.		in an an Albania
) [5	Status of ATR's	& any others		NO

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Ram Dolar charland DESIGNATION: Junior Engineer

(\$.