

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020	District: N. Champaran
Division : Narkatiaganj	Length (km): 3.900 Km
Name of the Road: Sitalpur to Bakulahiya	
Scheme/Programme: MAINTENANCE	
Package No.: RM/WT/NAR/19/0023	Road Id No.: 318089 02106
Status of the Project: Ongoing/Completed/Under Maintenance	Completed
Work is a case of: New Connectivity/Up gradation/ Maintenance	maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
f)	Contraction Joints provided or not (CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	-
2.	Cross Drainage	-
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	-
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

M. Ashraf
3-12-20
(Signature)

NAME: Md. Shahid Ashraf

DESIGNATION: Assistant Engineer