

FIELD INSPECTION REPORT

Date of Inspection : 04-12-2020		District: W. Champaran	
Division : Bagaha-1		Length (km): 6.50 km	
Name of the Road : Kothua to Bujurgu		Scheme/Programme: MAINTENANCE - MTR / BSE - New Maintenance Policy	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		✓SU
a)	Road Junction condition		✓SU
b)	Condition of Surfacing		✓SU
c)	Riding Quality		SU
d)	Road Camber		Yes/No ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		✓S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting		✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		16
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	✓
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

Signature

NAME: M. Shambhu Aka
DESIGNATION: J.E