FIELD INSPECTION REPORT

Date of Inspection: 03-12-2020		District: W. Chambaran	
Division: BACTAHA 1		Length (km): 4.035 Km	
		itak Paki Sadak Mirman	
Scheme/Programme:	MAINTENANCE	-M/R 3054 New Maintenance	Poilicy
Package No.:		Road Id No.:	in angus and the state of the second
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
the state of the s	Annual transport of the second	A STATE OF THE PARTY OF THE PAR	The second second

SI No.	Parameters to be checked	Romark		
1.	Pavement			
a)	Road Junction condition			
b)	Condition of Surfacing			
c)	Riding Quality			
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any	Yes/No		
7.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	√S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U		
c)	Condition of railings/slab/approach for Bridges	S/SRI/U		
3.	Road/Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No		
4.	Compliance History			
a)	Status of ATR's & any others	No		

Overall Rating

Satisfactory (S)		
Satisfactory but re	quires Improvement (SRI)	
Unsatisfactory (U)		

(Signature)

NAME: MD, Shehansheh Alam

DESIGNATION: OJE