## FIELD INSPECTION REPORT

		PIEDD INSPECTION REPORT	
Division Name of Scheme/ Package	the Road: P	MAINTENANCE MR-3054 (New Main E/BAG/19/0007 Road Id No.:	
	a case of:	Ongoing/Completed/Under Maintenance	-
Sl. No.		New Connectivity/Up gradation/ Maintenance	
1.	Pavement	Parameters to be checked	Remarks
		Total Control	
a)	Road Junction	S/U	
b)	Condition of S	S/U	
c)	Riding Quality	√S/U	
d)	Road Camber		
e)	Whether free	from defects such as visible cracks, exposed	S/U
	aggregates in case of CC Pavement.  Yes/No.		
f)	Contraction Joints provided or not (CC Pavement)  Yes/No.		
g)	Compaction of flank/slone & raincute if		
2.	Cross Drainage  Yes/No		
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U		
b)	Condition of Abutment & Wing walls Slab in D.C.		
c)	Condition of railings/slab/approach for Bridges		
	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	11 21.0503	S/SRI/U

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

Overall Rating

3.

a)

4.

a)

Satisfactory (S)	C
Satisfactory but requires Improvement (SRI)	(5)
Unsatisfactory (U)	

(Signature)

Yes/No

NAME: Deepak Kumar

Road Furniture

**Compliance History** 

Status of ATR's & any others

DESIGNATION: J.E