FIELD INSPECTION REPORT

1. Pavement a) Road Junction condition b) Condition of Surfacing c) Riding Quality d) Road Camber	arya.
Name of the Road: Najra Gofalbur Path Maranmat K Scheme/Programme: MAINTENANCE M/R Package No.: Road Id No.: Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance Sl. No. Parameters to be checked R 1. Pavement a) Road Junction condition b) Condition of Surfacing c) Riding Quality d) Road Camber	arya.
Scheme/Programme: MAINTENANCE Package No.: Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance Sl. No. Parameters to be checked 1. Pavement a) Road Junction condition b) Condition of Surfacing c) Riding Quality d) Road Camber	0
Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance Sl. No. Parameters to be checked R 1. Pavement a) Road Junction condition b) Condition of Surfacing c) Riding Quality d) Road Camber	
Work is a case of: New Connectivity/Up gradation/ Maintenance Sl. No. Parameters to be checked R 1. Pavement a) Road Junction condition b) Condition of Surfacing c) Riding Quality d) Road Camber	n 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Sl. No. Parameters to be checked R 1. Pavement a) Road Junction condition b) Condition of Surfacing c) Riding Quality d) Road Camber	
1: Pavement a) Road Junction condition b) Condition of Surfacing c) Riding Quality d) Road Camber	
a) Road Junction condition b) Condition of Surfacing c) Riding Quality d) Road Camber	lemarks
b) Condition of Surfacing c) Riding Quality d) Road Camber	Silvery I
c) Riding Quality d) Road Camber	S/H
d) Road Camber	S/IJ
the state of the s	S/U-
Whather for for defects quely as winths and	S/H
whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f) Contraction Joints provided or not (CC Pavement)	Yes/No
g) Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage	
a) Condition of head walls in Hume pipe culverts including its painting	S/SRI/J
b) Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
e) Condition of railings/slab/approach for Bridges	~ /***
3. Road Furniture	S/SRI/U

Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained

Overall Rating

a)

a)

	and the second
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	C. In the Market

(Signature)

Yes/No

NO.

NAME: SYED SHAEQUE AHMAD DESIGNATION: ASSI. Engineer,

Compliance History

Status of ATR's & any others