

FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020 District: Nalanda
 Division: Hilsa Length (km): - 3.108km
 Name of the Road: Dumasi to Sahaspur Road
 Scheme/Programme: MAINTENANCE ✓
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

ongoing
upgradation

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Y No
f)	Contraction Joints provided or not (CC Pavement)	Y No
g)	Compaction of flank/slope & raincuts if any	Y No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SR
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SR
c)	Condition of railings/slab/approach for Bridges	S SR
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Y No
4.	Compliance History	
a)	Status of ATR's & any others	

ongoing
work

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

"S" Satisfactory

Signature
2/12/2020
(Signature)

NAME:

Ganesh Kumar Rajan

JE / Parbharpur