

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: Madhubani
Division : Phulparas		Length (km): 1.92 km
Name of the Road: Sugapati to Kalapatti		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 31909908023
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. C.C. Pavement Not Provided	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement) — do —	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	Not available

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Maintenance items are not provide

(Signature)

NAME:

DESIGNATION:

[Signature]
03.12.2020
J.E.

[Signature]
03/12/2020
AE