

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: Samastipur
Division : Patna	Length (km): 2.44 K.M.
Name of the Road: Repair of Road from Shalpur Undi p.w. Road (East of Rly station)	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U - S
b)	Condition of Surfacing	✓S/U - S
c)	Riding Quality	✓S/U - S
d)	Road Camber	✓S/U - S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No - Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - S
g)	Compaction of flank/slope & raincuts if any	Yes/No - S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U - N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME: AJAY KUMAR SINGH
DESIGNATION: J. E.

03/12/2020
(Signature)